



Dr. Ing. Leonardo Bonini INGEGNERIA della SICUREZZA, AMBIENTE e della QUALITA'



BULLETIN No. 1/ 2013

CLICK THE OBLIGATION TO REPLACEMENT OF NOT PANIC CE

By February 18, 2013 must be replaced devices that are not CE marked for opening doors installed along the escape routes with respect to safety in case of fire.

These devices must be in accordance with UNI EN 179 and UNI EN 1125 and DPR April 21, 1993, n. 246, should be marked CE.

Compliance with the UNI EN 179 or the UNI EN 1125 depends on the type of activity and the number of people who have run out.

The Studio Dr. Ing. Leonardo Bonini is available for the necessary assessment.

Bologna 05/02/2013

Studio Dr. Ing. Leonardo Bonini



Intertek STUDIO CERTIFICATO UNI EN ISO 9001:2008 Intertek Certificato No. 1215872

Via Galliera n°34, 40121 BOLOGNA Tel.: +39 051 240 241-FAX: +39 051 716 032 3 E-mail: bonini.leonardo@tiscali.it

Web: www.leonardobonini.com